



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

April 25, 2007

Supervisor JCRH

**Mine Name:** Promontory Point West Quarry  
**Operator Name:** Kerry's Inc.

**Permit number:** S/003/057  
**Inspection Date:** April 12, 2007  
**Time:** 10:30 am

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** none

**Mine Status:** Permitted, No Activity

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Check status of this quarry, operator considering closing permit vs. posting reclamation surety at this time.

#### Inspection Summary:

This site was permitted on August 30, 2000. The operator was hopeful to get a contract from the railroad for riprap along the great salt lake causeway (this was unsuccessful). The area had been previously disturbed with sagebrush and rabbit brush dominating the pads and dump slopes (this disturbance was determined to be pre-law). During this inspection, particular attention was given as to whether there had been any recent activity. Apparently there has been no disturbance or activity at this site since it was permitted.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

This site could be closed, if the operator makes a formal request to do so. Otherwise, the operator should provide a reclamation surety and reclamation contract for this site.

**Inspector's Signature** LK

LK:pb

O:\M003-BoxElder\S0030057-PromontoryPointWest\inspections\Insp-04122007.doc